

CRITICAL INSTRUCTIONS

Part Number:
786137-5001S
786137-5003S

Application: **Vauxhall Insignia**

WHEN FITTING THIS TURBO, IT IS **CRITICAL** THE FOLLOWING INSTRUCTIONS ARE ADHERED TO:

- **Check/Replace swirl flaps**

It is essential that the swirl flaps in the inlet manifold, are checked for damage and correct operation. Replace as required. Failure to check/replace the swirl flaps may result in damage to the turbocharger.



Broken swirl flap fragments
can enter the turbo.

Any questions regarding the above should be directed to the supplier of this unit before commencing any work

